

Weekly Manual Cleaning Regime

Wash the Arctic PVC® sheets using a soft cloth with water or diluted soap/detergent.

Important Information:

Only use a soft cloth.
Never use an abrasive cleaner, wire wool or pads.

Pressure Cleaning

Pressure cleaning with hot water may be carried out with the nozzle a minimum of 600mm (approximately 2 feet) away from the surface area (Arctic sheet).

Important Information:

Never exceed the maximum temperature of 60°C on any Arctic PVC® sheet.

Stubborn Stains

Any heavily soiled areas/stains can be cleaned with a non abrasive cleaner such as Jif/Cif.

Dusty Environments

To reduce static charge after cleaning, apply an antistatic solution to all surfaces when dry if required.

Important Notice: Failure to maintain Arctic PVC® products in accordance with recommended procedure can affect the performance of the sheets.

Helpful Tips

There is no better nor proven effective remedy to eliminate bacteria than that of an impeccable cleaning regime.

Develop a cleaning and maintenance regime that is suited to the usage and traffic of the environment. Identify high usage/traffic areas and adapt the cleaning regime accordingly. Seldom used areas it is advised that a minimum cleaning regime is weekly.

Only use the cleaning chemicals mentioned above. Never mix chemicals together and use on any Arctic PVC® sheet, trim or weld detail.

Scuff marks and heavily soiled areas should be removed daily or more often than a weekly minimum cleaning regime.

Hot water pressure washers can cause damage as outlined above if the temperature is too high and the nozzle is too close.